




SUPPLEMENT


BAND SAW AND SHAFT

- 1 G 1x8"
- 4 G 1x3"
- 4 G 1/2x6"
- 2 G 1/2x4"
- 8 G 1/2x3"
- 3 G 1/2x2"
- 1 PL 3x3"
- 4 SF 1"
- 6 C 1/2"
- 2 RA 1"
- 6 RA 1/2"
- 2 DW 2 1/2"
- 2 W 2 1/2"
- 4 PW
- 1 P Disc
- 1 S 6"
- 2 S 4"
- 6 CL

Made with No. 3 Set
TO MOTOR



BAND SAW




GOVERNOR

GOVERNOR

- 4 G 1x8"
- 3 G 1x4"
- 2 G 1x3"
- 2 G 1/2x10"
- 4 G 1/2x4"
- 2 SF 1"
- 1 C 1"
- 4 RA 1"
- 2 RA 1/2"
- 2 A 1/2"
- 5 DW 2 1/2"
- 1 W 2 1/2"
- 2 P Disc
- 2 PW
- 4 SW
- 1 S 7"
- 1 S 3"
- 2 S 2"
- 2 CL


Made with No. 5 Set

FERRIS WHEEL



Made with No. 5 Set

- | | |
|-------------|-------------|
| 3 C 1" | 4 G 1x8" |
| 8 C 1/2" | 4 G 1x4" |
| 4 G 1x3" | 4 G 1x3" |
| 4 G 1x10" | 4 G 1x8" |
| 6 RA 1" | 8 G 1/2x6" |
| 8 RA 1/2" | 8 G 1/2x6" |
| 3 A 1/2" | 4 G 1/2x4" |
| 2 A 1" | 1 GN 1/2x6" |
| 4 DW 2 1/2" | 4 G 1/2x4" |
| 1 P Disc | 8 G 1/2x3" |
| 4 PW | 4 G 1/2x2" |
| 3 SW | 1 PL 4x4" |
| 1 S 7" | 2 PL 3x3" |
| 4 S 4" | 2 PL 3x2" |
| 1 S 3" | 8 SF 1" |
| 10 CL | 8 SF 2" |



WIND MILL



- | | |
|------------|-------------|
| 1 G 1x8" | 8 SF 3" |
| 4 G 1x4" | 4 SFC 3" |
| 2 G 1x3" | 6 SF 2" |
| 2 WPA 3x3" | 6 SF 1" |
| 2 PA 3x3" | 2 CB 1" |
| 2 WPA 2x3" | 4 RA 1" |
| 2 PA 2x3" | 2 RA 1/2" |
| 1 HPA 3x2" | 1 W 2 1/2" |
| 2 HPA 3x1" | 4 DW 2 1/2" |
| 4 TPA 3x6" | 1 PW |
| 4 TPA 2x6" | 1 SW |
| 1 PL 4x4" | 2 P Disc |
| 2 PL 3x3" | 2 S 6" |
| 2 HPL | 8 CL |
| 4 SF 6" | |

Made with No. 5 Set


BEAM ENGINE

- | | |
|-------------|-------------|
| 2 G 1x4" | 3 RA 1" |
| 3 G 1x3" | 8 RA 1/2" |
| 4 G 1/2x10" | 4 A 1/2" |
| 8 G 1/2x8" | 2 UA 1" |
| 9 G 1/2x6" | 5 DW 2 1/2" |
| 4 G 1/2x4" | 1 W 2 1/2" |
| 8 G 1/2x3" | 1 PW |
| 2 G 1/2x2" | 2 S 7" |
| 1 PL 3x10" | 1 S 6" |
| 1 PL 3x6" | 2 S 4" |
| 1 PL 3x4" | 1 S 2" |
| 8 SF 1" | 10 CL |
| 1 C 1" | 1 TNC |
| 7 C 1/2" | |

Made with No. 5 Set



FORWARD AND REVERSE FRICTION DRIVE




Made with No. 5 Set

PARTS FOR FRAME

- 3 G 1x8"
- 1 G 1x4"
- 2 G 1x3"
- 2 G 1/2x4"
- 3 G 1/2x3"
- 2 CB 1"
- 1 C 1/2"
- 4 RA 1"
- 5 RA 1/2"

BELT TO MOTOR



Parts for
Friction Drive
can be purchased
separate.
Price \$1.00

PARTS FOR SHAFTING AND PULLEYS



- 4 DW 2 1/2"
- 1 W 2 1/2"
- 3 P Disc
- 1 P W
- 1 S 7"
- 1 S 6"
- 5 CL

WATER WHEEL

OLD MILL

- | | |
|-------------|-------------|
| 2 G 1x8" | 2 HPL |
| 4 G 1x4" | 4 RA 1" |
| 3 G 1x3" | 2 UA 1" |
| 7 G 1/2x6" | 4 C 1/2" |
| 2 GN 1/2x6" | 6 RA 1/2" |
| 3 G 1/2x4" | 4 A 1/2" |
| 8 G 1/2x3" | 4 DW 2 1/2" |
| 2 WPA 2x3" | 2 P Disc |
| 2 PK 3" | 1 S 7" |
| 2 PL 4x4" | 1 S 3" |
| 2 PL 3x8" | 8 SF 1" |
| 1 PL 3x6" | 2 SF 4" |
| 2 PL 3x2" | 8 CL |
| 2 PL 3x1" | |

Made with No. 5 Set




Speed Increaser and Reducer

- 2 G 1x8"
- 2 G 1x3"
- 4 G 1/2x3"
- 2 1" CB
- 2 1/2" CB
- 1 3x8" PL
- 4 1" SF
- 2 6" Shaft
- 2 PW" DW
- 4 2 1/2" DW
- 2 P Disc
- 4 CL


Made with No. 5 Set

FAST SPEED

SLOW SPEED



PULLEY DISC



LIST OF MODELS THAT CAN BE DRIVEN WITH MOTOR (in book of Models)

No. 1 Set

Wind Mill
Drill Press
Air Swing

No. 3 Set

Lathe
Revolving Crane (with Friction Drive)
Airport Indicator
Trip Hammer
Steam Shovel (with Friction Drive)
Tow Car (with Friction Drive)
Traveling Crane (with Friction Drive)
Wind Mill
Sand Wheel
Air Ride
Portable Pile Driver
Stationary Pump

No. 5 Set

Steam Shovel (with Friction Drive)
Printing Press
Derrick (with Friction Drive)
Airplane
Overhead Traveling Crane (with Friction Drive)
Overhead Traveling Crane (with Friction Drive)

STEEL BUILDER CO., Inc.
NEWARK, N. J., U. S. A.

